LAND REGENERATION



EOV Report
Remény Farm

REMÉNY FARM
TISZTA ÉLELMISZEREK

Baseline Monitoring 04.-06.07.2023

Hub für Holistic Management

Mail: info@landregeneration.de
Web: http://landregeneration.de/

savory network

Remény Farm |04.-06.07.2023

Summary

Insights:

- Energy Flow and Community Dynamics lowest function
- Warm season grasses not yet present
- Overall stable ecosystem function (EHI 18)
- Other observations: Bare ground present, litter not at best, low vigour of cool season grasses → Maybe intensify animal impact (not grazing).

Next steps for management:

- ...
- ...
- ...

On which indicator would you like to focus in the next year? What will you change, apply, or continue in the next year to move further towards your holistic context?

LAND REGENERATION

Remény Farm |04.-06.07.2023

EOV Monitoring – Overview (1/2)

Year	Landbase EHI (-140 to 120)
2023	18.0
2024	
2025	

Degenerates -140 bis -70 | 1-30 | Regenerates 60-120

Year	Water cycle	Mineral cycle	Energy flow	Community dynamics
2023	**79 %**	**71 %**	**52 %**	**50 %**
2024				
2025				

0% - 20% | 80% - 100%

Ecological Health Index (EHI)

The Evaluation Matrix is a contextually relevant set of leading ecological indicators. Landbases are monitored using the Evaluation Matrix and receive an Ecological Health Index (EHI) score that is calibrated to their Ecoregion.

The EHI Score serves as an aggregated measure of ecosystem health and is based upon ecological indicators associated with the four ecosystem processes - Water Cycle. Mineral Cycle, Energy Flow, and Community Dynamics.

The EHI Score is the weighted average EHI score for an entire landbase.

EHI scores above 30 points indicate adequate ecosystem function. Values above 65 points indicate a low deviation from the ecoregion's potential.

Scores between 0 and 30 indicate moderate deviation from potential, while negative scores indicate ineffective ecosystem processes and current degradation processes.

Remény Farm |04.-06.07.2023

EOV Monitoring – Overview (2/2)

Monitoring site		Landbase EHI (-140 to 120)		
		2023	2024	2025
P9	1	**-5**		
P8	2	**5**		
P12	3	**15**		
P12	4	**30**		
P14	5	**5**		
P6	6	**-5**		
P3	7	**60**		
P1	8	**55**		
P2	9	**-15**		
P0	10	**35**		

Degenerates -140 bis -70 ← → **1-30** → **Regenerates 60-120**

Ecological Health Index (EHI)

The Evaluation Matrix is a contextually relevant set of leading ecological indicators. Landbases are monitored using the Evaluation Matrix and receive an Ecological Health Index (EHI) score that is calibrated to their Ecoregion.

The EHI Score serves as an aggregated measure of ecosystem health and is based upon ecological indicators associated with the four ecosystem processes - Water Cycle. Mineral Cycle, Energy Flow, and Community Dynamics.

The EHI Score is the weighted average EHI score for an entire landbase.

EHI scores above 30 points indicate adequate ecosystem function. Values above 65 points indicate a low deviation from the ecoregion's potential.

Scores between 0 and 30 indicate moderate deviation from potential, while negative scores indicate ineffective ecosystem processes and current degradation processes.

Remény Farm |04.-06.07.2023

Overview monitoring sites

∅ Rainfall: 600 mm

2022: 407 mm

2023 (Jan-July): 376 mm

Brittleness
5-6

Comments: In the middle of the brittleness scale, tools need to be monitored closely on their effect.

Paddock name	STM Site	State		Coordinates	
P9	1	IIIa)	Grassland	*48.074631*	*20.274618*
P8	2	IIIa)	Grassland	*48.07442*	*20.275103*
P12	3	IIIa)	Grassland	*48.071779*	*20.278642*
P12	4	IIIa)	Grassland	*48.070558*	*20.278356*
P14	5	IIIa)	Grassland	*48.069488*	*20.277393*
P6	6	IIIa)	Grassland	*48.066909*	*20.272077*
P3	7	IIIb)	Grassland	*48.064576*	*20.27333*
P1	8	IIIa)	Grassland	*48.064837*	*20.276209*
P2	9	I -> II	Forest	*48.063379*	*20.275955*
P0	10	IIIa)	Grassland	*48.071205*	*20.278368*
P14	LTM 1-1	IIIa)	Grassland	*48.069814°*	*20.276441°*
	LTM 1-3			*48.069738°*	*20.276471°*
	LTM 1-6			*48.069622°*	*20.276519°*

Remény Farm |04.-06.07.2023

Overview monitoring sites

Remény Farm | 04.-06.07.2023

EOV Monitoring STM – Baseline year

Total EHI	EHI Scores between 0 and 30 indicate moderate deviation from potential.
18	

Water cycle Index	Mineral cycle Index	Energy flow Index	Community dynamics Index
79 %	71 %	52 %	51 %

Paddock name	STM Site	State		Live canopy abundance	Living organisms	FG 1: Warm season grasses	FG 2: Cool season grasses	FG 3: Forbs & Legumes	FG 4: Trees & Shrubs	Context. desired rare species	Context. undesired species	Litter abundance	Litter decomp.	Dung decomp.	Bare ground	Capping	Wind erosion	Water erosion	Total Score
P9	1	*IIIa)*	*Grassland*	-10	0	-10	0	5	-5	10	0	5	5	10	0	-5	0	-10	**-5**
P8	2	*IIIa)*	*Grassland*	-10	5	-10	10	-5	-5	0	-5	5	5	10	10	-5	0	0	**5**
P12	3	*IIIa)*	*Grassland*	-10	10	-10	0	5	5	0	0	5	5	5	0	0	0	0	**15**
P12	4	*IIIa)*	*Grassland*	-5	10	-10	0	5	10	0	0	5	5	10	10	-5	0	0	**35**
P14	5	*IIIa)*	*Grassland*	-10	10	-10	0	5	0	0	0	0	5	5	0	0	0	0	**5**
P6	6	*IIIa)*	*Grassland*	-10	5	-10	-5	0	-5	5	0	0	5	5	10	-5	0	0	**-5**
P3	7	*IIIb)*	*Grassland*	-5	10	-10	10	10	5	0	-5	5	10	10	20	0	0	0	**60**
P1	8	*IIIa)*	*Grassland*	-5	10	-10	5	10	5	0	0	10	10	10	10	0	0	0	**55**
P2	9	*I -> II*	*Forest*	0	0	-10	-5	-10	0	0	-10	5	5	10	0	0	0	0	**-15**
P0	10	*IIIa)*	*Grassland*	5	10	-10	10	0	-10	0	-5	10	5	10	10	0	0	0	**35**

Degenerates ← → Regenerates

Remény Farm |04.-06.07.2023

EOV Long Term Monitoring #1 – Overview

P14	LTM 1-1	IIIa)	Grassland	*48.069814°*	*20.276441°*
	LTM 1-3			*48.069738°*	*20.276471°*
	LTM 1-6			*48.069622°*	*20.276519°*

Remény Farm |04.-06.07.2023

EOV Long Term Monitoring #1 – Details EHI

Photographic plot

EHI
-5

EHI scores between 0 and 30 indicate moderate deviation from potential.

Date	Live canopy abundance	Living organisms	FG1: Warm-season grasses	FG2: Cold-sea songrasses	FG3: Forbs & legumes	FG4: Trees & shrubs	Contextual. desired rare species	Contextual. undesired species	Litter abundance	Litter decompo-sition	Dung decompo-sition	Bare ground	Capping	Wind erosion	Wasser erosion	EHI
Juli 23	-10	10	-10	0	10	-5	0	0	0	5	10	-10	-5	0	0	-5
2028																
2033																

Degeneriert ← → Regeneriert

Year	Water cycle	Mineral cycle	Energy flow	Community dynamics
2022	55 %	28 %	17 %	39 %
2023				
2024				

0% - 20% ← → **80% - 100%**

Remény Farm |04.-06.07.2023

EOV Long Term Monitoring #1 – Details Diversity

Transect 1&2

Observations



Vegetative cover and functional groups

Bare ground	0.5%
Litter	6.54%
Rocks	0%
Mosses, lichen, algae	0%
Warm season grasses	0%
Cool season grasses	62.38%
Legumes	20.95%
Other forbs	6.03%
Sedges & rushes	0%
Trees	0.02%
Shrubs	2.09%
Annuals	0.5%

Water infiltration

Min.	Rate
6.23 Min	3.92 (mm/min)
>30 Min	00.63 (mm/min)
4.13 Min	5.93 (mm/min)
0.33 Min	45.45 (mm/min)

Minutes for infiltration of 25mm of rain - after pre-wetting with same amount.

Very high

High 6

Medium 10

Low 30

Very low 40

Comment:
45.45 rate: No water to the sides, pre-wetting as fast as the soaking.

Shannon-Index (Biodiversity)

3.96 Very high range

Very low <2.0 | Low 2.0-2.49 | Medium 2.5-2.99 | High 3-3.49 | Very high >3.5

The Shannon Wiener Diversity Index combines the effects of species richness and evenness with biomass distribution. Communities with even distribution of biomass get higher values, whilst those that have strong dominance of a few species get smaller values. Values range from 0 to 5.

Species diversity

29

Very low 0 | Low 15 | Medium 25 | High 35 | Very high 45

Species Richness is a measure of the number of different plant species encountered in the Long Term Monitoring transect.

Remény Farm |04.-06.07.2023

EOV Long Term Monitoring #1 – Details Transect 3

Baseline





2024

Baseline





2024

Remény Farm |04.-06.07.2023

EOV Soil Samples – Details

Not all soil samples done during the baseline monitoring - list needs to be updated.

No.	Sample Name	Coordinates		Date	Strata	No. sub samples	Average depth (cm)	Fresh weight (gr)	Probe diameter	Comments
1	GLR-REM-STM1-1	48.07463	20.274618	04.07.2023	Grassland	3	0-30	995	3	
2	GLR-REM-STM1-2	48.07442	20.275103	04.07.2023	Grassland	3	0-30	1255	3	
3	GLR-REM-STM2-1	48.07442	20.275103	04.07.2023	Grassland	3	0-30	1265	3	
4	GLR-REM-STM2-2	48.07229	20.274829	04.07.2023	Grassland	3	0-30	1325	3	
5	GLR-REM-STM3-1	48.07177	20.278642	05.07.2023	Grassland	3	0-30	1075	3	
6	GLR-REM-STM3-2	48.071205	20.278368	05.07.2023	Grassland	3	0-30	1315	3	
7	GLR-REM-STM4-1	48.070558	20.278356	05.07.2023	Grassland	3	0-30	1210	3	
8	GLR-REM-STM4-2						0-30		3	
9	GLR-REM-STM5-1	48.069488	20.277393	05.07.2023	Grassland	1	0-30	435	3	Soil sampler broke, only 1 of 3 sub samples.
10	GLR-REM-STM5-2						0-30		3	
11	GLR-REM-STM6-1	48.066909	20.272077		Grassland		0-30		3	
12	GLR-REM-STM6-2						0-30		3	
13	GLR-REM-STM7-1	48.064576	20.27333		Grassland		0-30		3	
14	GLR-REM-STM7-2						0-30		3	
15	GLR-REM-STM8-1	48.064837	20.276209		Grassland		0-30		3	
16	GLR-REM-STM8-2						0-30		3	
17	GLR-REM-STM9-1	48.063379	20.275955		Forest		0-30		3	
18	GLR-REM-STM9-2						0-30		3	
19	GLR-REM-STM10-1						0-30		3	
20	GLR-REM-STM10-2	48.071205	20.278368	09.07.2023	Grassland	2	0-30	605	3	Soil sampler broke, only 2 of 3 sub samples.

LAND REGENERATION

Remény Farm |04.-06.07.2023

EOV STM – #1

Paddock name	STM Site	State		Coordinates		Comment
P9	1	*IIIa)*	*Grassland*	*48.074631*	*20.274618*	*No animals since last year (Sep.), Moss, slope, south-west*

Date	Live canopy abundance	Living organisms	FG 1: Warm season grasses	FG 2: Cool season grasses	FG 3: Forbs & Legumes	FG 4: Trees & Shrubs	Context. desired rare species	Context. undesired species	Litter abundance	Litter decomp.	Dung decomp.	Bare ground	Capping	Wind erosion	Water erosion	Total Score
04.07.2023	-10	0	-10	0	5	-5	10	0	5	5	10	0	-5	0	-10	-5
2024																
2025																

Degeneriert ← → Regeneriert

Date	ADH	Forage Quality	Use pattern	Use intensity
2023	50	3	PG	n
2024				
2025				

Water cycle	60%
Mineral cycle	56%
Energy flow	33%
Community Dynamics	50%

0% - 20% ← → 80% - 100%

Forage Quality
5 100% green leaves, with legumes
4 100% green material, mainly leafs and new stems-No legumes
3 Green material with high proportion of stems and a proportion up to 40% of dead material
2 Stems and dead leafs predominant. Some green mixed in.
1 Stems and dead leaves predominant. Old material. Very little or no green at all.

Photos	
Baseline	2024
	Horizon
	45°
	90°

LAND REGENERATION

Remény Farm |04.-06.07.2023

EOV STM – #2

Paddock name	STM Site	State		Coordinates		Comment
P8	2	*IIIa)*	*Grassland*	*48.07442*	*20.275103*	*Valley, grazed for 1 day 16 days ago Chickens, cattle, good quality pasture*

Date	Live canopy abundance	Living organisms	FG 1: Warm season grasses	FG 2: Cool season grasses	FG 3: Forbs & Legumes	FG 4: Trees & Shrubs	Context. desired rare species	Context. undesired species	Litter abundance	Litter decomp.	Dung decomp.	Bare ground	Capping	Wind erosion	Water erosion	Total Score
04.07.2023	-10	5	-10	10	-5	-5	0	-5	5	5	10	10	-5	0	0	5
2024																
2025																

Degeneriert ← → Regeneriert

Date	ADH	Forage Quality	Use pattern	Use intensity
2023	25	3	PG	i
2024				
2025				

Water cycle	80%
Mineral cycle	72%
Energy flow	50%
Community Dynamics	46%

0% - 20% ← → 80% - 100%

Forage Quality

5	100% green leaves, with legumes
4	100% green material, mainly leafs and new stems-No legumes
3	Green material with high proportion of stems and a proportion up to 40% of dead material
2	Stems and dead leafs predominant. Some green mixed in.
1	Stems and dead leaves predominant. Old material. Very little or no green at all.

Photos	
Baseline	**2024**
	Horizon
	45°
	90°

Remény Farm |04.-06.07.2023

EOV STM – #3

Paddock name	STM Site	State		Coordinates		Comment
P12	3	*IIIa)*	*Grassland*	*48.071779*	*20.278642*	*Slope, 2x grazed last year (end of July 2022) Shrubs present, south-facing*

Date	Live canopy abundance	Living organisms	FG 1: Warm season grasses	FG 2: Cool season grasses	FG 3: Forbs & Legumes	FG 4: Trees & Shrubs	Context. desired rare species	Context. undesired species	Litter abundance	Litter decomp.	Dung decomp.	Bare ground	Capping	Wind erosion	Water erosion	Total Score
04.07.2023	-10	10	-10	0	5	5	0	0	5	5	5	0	0	0	0	15
2024																
2025																

Degeneriert ← → Regeneriert

Date	ADH	Forage Quality	Use pattern	Use intensity
2023	44	3	PG	s
2024				
2025				

Water cycle	75%
Mineral cycle	61%
Energy flow	33%
Community Dynamics	50%

0% - 20% ← → 80% - 100%

Forage Quality

5	100% green leaves, with legumes
4	100% green material, mainly leafs and new stems-No legumes
3	Green material with high proportion of stems and a proportion up to 40% of dead material
2	Stems and dead leafs predominant. Some green mixed in.
1	Stems and dead leaves predominant. Old material. Very little or no green at all.

Photos	
Baseline	2024
	Horizon
	45°
	90°

Remény Farm |04.-06.07.2023

EOV STM – #4

Paddock name	STM Site	State		Coordinates		Comment
P12	4	*IIIa)*	*Grassland*	*48.070558*	*20.278356*	*Slope, trees + shrubs present, no key species of grasses present, north-east-facing*

Date	Live canopy abundance	Living organisms	FG 1: Warm season grasses	FG 2: Cool season grasses	FG 3: Forbs & Legumes	FG 4: Trees & Shrubs	Context. desired rare species	Context. undesired species	Litter abundance	Litter decomp.	Dung decomp.	Bare ground	Capping	Wind erosion	Water erosion	Total Score
04.07.2023	-5	10	-10	0	5	5	0	0	5	5	10	10	-5	0	0	30
2024																
2025																

Degeneriert ← → Regeneriert

Date	ADH	Forage Quality	Use pattern	Use intensity
2023				
2024				
2025				

Water cycle	80%
Mineral cycle	78%
Energy flow	58%
Community Dynamics	57%

0% - 20% ← → 80% - 100%

Forage Quality
5 100% green leaves, with legumes
4 100% green material, mainly leafs and new stems-No legumes
3 Green material with high proportion of stems and a proportion up to 40% of dead material
2 Stems and dead leafs predominant. Some green mixed in.
1 Stems and dead leaves predominant. Old material. Very little or no green at all.

Photos	
Baseline	**2024**
	Horizon
	45°
	90°

Remény Farm |04.-06.07.2023

EOV STM – #5

Paddock name	STM Site	State		Coordinates		Comment
P14	5	*IIIa)*	*Grassland*	*48.069488*	*20.277393*	*Slope, south-facing*

Date	Live canopy abundance	Living organisms	FG 1: Warm season grasses	FG 2: Cool season grasses	FG 3: Forbs & Legumes	FG 4: Trees & Shrubs	Context. desired rare species	Context. undesired species	Litter abundance	Litter decomp.	Dung decomp.	Bare ground	Capping	Wind erosion	Water erosion	Total Score
04.07.2023	-10	10	-10	0	5	0	0	0	0	5	5	0	0	0	0	5
2024																
2025																

Degeneriert ← → Regeneriert

Date	ADH	Forage Quality	Use pattern	Use intensity
2023				
2024				
2025				

Water cycle	70%
Mineral cycle	56%
Energy flow	33%
Community Dynamics	46%

0% - 20% ← → 80% - 100%

Forage Quality
5 100% green leaves, with legumes
4 100% green material, mainly leafs and new stems-No legumes
3 Green material with high proportion of stems and a proportion up to 40% of dead material
2 Stems and dead leafs predominant. Some green mixed in.
1 Stems and dead leaves predominant. Old material. Very little or no green at all.

Photos	
Baseline	**2024**
	Horizon
	45°
	90°

Remény Farm |04.-06.07.2023

EOV STM – #6

Paddock name	STM Site	State		Coordinates		Comment
P6	6	*IIIa)*	*Grassland*	*48.066909*	*20.272077*	*Slope, west-facing* *Grazed last year*

Date	Live canopy abundance	Living organisms	FG 1: Warm season grasses	FG 2: Cool season grasses	FG 3: Forbs & Legumes	FG 4: Trees & Shrubs	Context. desired rare species	Context. undesired species	Litter abundance	Litter decomp.	Dung decomp.	Bare ground	Capping	Wind erosion	Water erosion	Total Score
04.07.2023	-10	5	-10	-5	0	-5	5	0	0	5	5	10	-5	0	0	-5
2024																
2025																

Degeneriert ← → Regeneriert

Date	ADH	Forage Quality	Use pattern	Use intensity
2023				
2024				
2025				

Water cycle	75%
Mineral cycle	61%
Energy flow	50%
Community Dynamics	46%

0% - 20% ← → 80% - 100%

Forage Quality

5	100% green leaves, with legumes
4	100% green material, mainly leafs and new stems-No legumes
3	Green material with high proportion of stems and a proportion up to 40% of dead material
2	Stems and dead leafs predominant. Some green mixed in.
1	Stems and dead leaves predominant. Old material. Very little or no green at all.

Photos	
Baseline	2024
	Horizon
	45°
	90°

Remény Farm |04.-06.07.2023

EOV STM – #7

Paddock name	STM Site	State		Coordinates		Comment
P3	7	*IIIb)*	*Grassland*	*48.064576*	*20.27333*	Slope, Last grazed 23.05., young wild fruit trees, north-east

Date	Live canopy abundance	Living organisms	FG 1: Warm season grasses	FG 2: Cool season grasses	FG 3: Forbs & Legumes	FG 4: Trees & Shrubs	Context. desired rare species	Context. undesired species	Litter abundance	Litter decomp.	Dung decomp.	Bare ground	Capping	Wind erosion	Water erosion	Total Score
04.07.2023	-5	10	-10	10	10	5	0	-5	5	10	10	20	0	0	0	60
2024																
2025																

Degeneriert ← → Regeneriert

Date	ADH	Forage Quality	Use pattern	Use intensity
2023	25	4	PG	n
2024				
2025				

Water cycle	95%
Mineral cycle	94%
Energy flow	75%
Community Dynamics	71%

0% - 20% ← → 80% - 100%

Forage Quality

5	100% green leaves, with legumes
4	100% green material, mainly leafs and new stems-No legumes
3	Green material with high proportion of stems and a proportion up to 40% of dead material
2	Stems and dead leafs predominant. Some green mixed in.
1	Stems and dead leaves predominant. Old material. Very little or no green at all.

Photos	
Baseline	2024
	Horizon
	45°
	90°

Remény Farm |04.-06.07.2023

EOV STM – #8

Paddock name	STM Site	State		Coordinates		Comment
P1	8	*IIIa)*	*Grassland*	*48.064837*	*20.276209*	*Slope, south-west, trees + shrubs present Surrounded by (open) forest*

Date	Live canopy abundance	Living organisms	FG 1: Warm season grasses	FG 2: Cool season grasses	FG 3: Forbs & Legumes	FG 4: Trees & Shrubs	Context. desired rare species	Context. undesired species	Litter abundance	Litter decomp.	Dung decomp.	Bare ground	Capping	Wind erosion	Water erosion	Total Score
04.07.2023	-5	10	-10	5	10	5	0	0	10	10	10	10	0	0	0	55
2024																
2025																

Degeneriert ← → Regeneriert

Date	ADH	Forage Quality	Use pattern	Use intensity
2023	25	3	pg	s
2024				
2025				

Water cycle	90%
Mineral cycle	89%
Energy flow	58%
Community Dynamics	64%

0% - 20% ← → 80% - 100%

Forage Quality
5 100% green leaves, with legumes
4 100% green material, mainly leafs and new stems-No legumes
3 Green material with high proportion of stems and a proportion up to 40% of dead material
2 Stems and dead leafs predominant. Some green mixed in.
1 Stems and dead leaves predominant. Old material. Very little or no green at all.

Photos	
Baseline	2024
	Horizon
	45°
	90°

Remény Farm |04.-06.07.2023

EOV STM – #9

Paddock name	STM Site	State		Coordinates		Comment
P2	9	*I -> II*	*Forest*	*48.063379*	*20.275955*	*Closed forest to become open woodland for grazing, nettles*

Date	Live canopy abundance	Living organisms	FG 1: Warm season grasses	FG 2: Cool season grasses	FG 3: Forbs & Legumes	FG 4: Trees & Shrubs	Context. desired rare species	Context. undesired species	Litter abundance	Litter decomp.	Dung decomp.	Bare ground	Capping	Wind erosion	Water erosion	Total Score
04.07.2023	0	0	-10	-5	-10	0	0	-10	5	5	10	0	0	0	0	-15
2024																
2025																

Degeneriert ← → Regeneriert

Date	ADH	Forage Quality	Use pattern	Use intensity
2023	33	4	pg	i
2024				
2025				

Water cycle	75%
Mineral cycle	56%
Energy flow	50%
Community Dynamics	25%

0% - 20% ← → 80% - 100%

Forage Quality
5 100% green leaves, with legumes
4 100% green material, mainly leafs and new stems-No legumes
3 Green material with high proportion of stems and a proportion up to 40% of dead material
2 Stems and dead leafs predominant. Some green mixed in.
1 Stems and dead leaves predominant. Old material. Very little or no green at all.

Photos	
Baseline	**2024**
	Horizon
	45°
	90°

Remény Farm |04.-06.07.2023

EOV STM – #10

Paddock name	STM Site	State		Coordinates		Comment
P0	10	*IIIa)*	*Grassland*	*48.071205*	*20.278368*	*3 times grazed this year with chickens (> 1000) Last grazed 9 days ago, valley*

Date	Live canopy abundance	Living organisms	FG 1: Warm season grasses	FG 2: Cool season grasses	FG 3: Forbs & Legumes	FG 4: Trees & Shrubs	Context. desired rare species	Context. undesired species	Litter abundance	Litter decomp.	Dung decomp.	Bare ground	Capping	Wind erosion	Water erosion	Total Score
04.07.2023	5	10	-10	10	0	-10	0	-5	10	5	10	10	0	0	0	35
2024																
2025																

Degeneriert ← → Regeneriert

Date	ADH	Forage Quality	Use pattern	Use intensity
2023		3		pg
2024				
2025				

Water cycle	90%
Mineral cycle	83%
Energy flow	75%
Community Dynamics	46%

0% - 20% ← → 80% - 100%

Forage Quality

5	100% green leaves, with legumes
4	100% green material, mainly leafs and new stems-No legumes
3	Green material with high proportion of stems and a proportion up to 40% of dead material
2	Stems and dead leafs predominant. Some green mixed in.
1	Stems and dead leaves predominant. Old material. Very little or no green at all.

Photos	
Baseline	2024
	Horizon
	45°
	90°

Thank you!

If you have further questions, we look forward hearing from you.

Leon Bucher
mail: leon@landregeneration.de
web: http://landregeneration.de/

LAND REGENERATION